Monday, 5/14/2007 7:14:48 AM Date: Kim Johnston **Process Sheet** User: : HARNESS ASSEMBLY **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer : 32336 Job Number : 12858 Estimate Number : D412702109B Part Number : NA P.O. Number · ICA D412-702 P.79 **Drawing Number** S.O. No. : NIA : 5/14/2007 This Issue Project Number : N/A : NC Prsht Rev. : D : NA : SMALL /MED FAB **Drawing Revision** Type First Issue :NIA : NIA Material Previous Run Each : 5/15/2007 Due Date Written By Checked & Approved By Comment Additional Product Job Number: Description: Machine Or Operation: Seq. #: DOCUMENT CONTROL 1.0 Comment: DOCUMENT CONTROL type labels per PPP D412-702-109B CHG001 ADAPTER 2.0 D35733 5.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qtv.: ADAPTER B B3/862 SHOULDER HARNESS LH 3.0 D3579045 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Comment: Qty.: SHOULDER HARNESS RH batch: 133211 S) CLIP 4.0 K62 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Comment: Qty.: CLIP m104426 batch: Screw 5.0 MS24693S272 Comment: Qty.: 4.0000 Each(s)/Unit Total: 20,0000 Each(s) Screw m 8967 batch:

Done 1

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
07/05/16		w/o split	w	67/05/16	4	B745-16	125%

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date: 07/05/16
			QA: N/C Closed:	Date:

NCR:		V	VORK OR	DER NON-CONFORMANCI	E (NCR)			
DATE	STEP	Description of NC		Corrective Action Section B	Verification	Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
1		label D3569-3	Ve	Use contact cencent	201	//	07-05-16	//
07/05/16	3	label D3569-3 do not Stick	07,05.16	M102565	07/05/16		کھا ۔	
,				Use contact cenent M102565 SEE EMAIL ON V/0 32337	7/1/2	0705.16		10705-16
·				1 1/2 2005/				
		·						

NOTE: Date & initial all entries


Monday, 5/14/2007 7:14:48 AM er: Kim Johnston **Process Sheet** Drawing Name: HARNESS ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412702109B Job Number: 32336 Job Number: Description: Machine Or Operation: Seq. #: Washer 6.0 AN960JD10LL Comment: Qty.: 4.0000 Each(s)/Unit Total: 20.0000 Each(s) Washer batch: N MS21042L3 7.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 20.0000 Each(s) batch: DECAL D35693 8.0 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Comment: Qty.: DECAL B 32086 batch: SMALL & MEDIUM FAB RESOURCE 1 9.0 SMALL FAB 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per dwg ICA D412-702 p.79 INSPECT WORK TO CURRENT STEP 10.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 11.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-702-109B CHG001 Location: PPP Rev: Job Completion

Dart Aerospace Ltd


W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	•	PAR #: Pault Category: No	CR: Ye	s No DQ	A:	Date: _				
			QA:	N/C Close	d:	Date: _	·			

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)									
DATE		Description of NC		Verification	A	A								
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector						
					;									

NOTE: Date & initial all entries



DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES (BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES CONTROLLED COPY

(BFI TS AND D3560 1/2/2 DECAUSE ASSEMBLIES CONTROLLED COPY) (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

WITHOUT NOTICE

ENGINEERING

SHOP COPY RETURN TO

• COPYRIGHT @ 2004 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00